

PARTITION PROS

Maintenance Guide

646-453-4564
info@thepartitionpros.com
www.thepartitionpros.com

Maintenance Procedure

FOR PHENOLIC BLACK CORE MATERIAL

Cleaning Instructions

1. To clean product's surface, use a damp cloth or sponge and a mild soap or detergent. Rinse thoroughly with warm water and wipe dry. Do not use abrasive pads or steel wool.

2. Phenolic placed in high humidity areas must be properly ventilated.

3. If a spill occurs on product's surface, wipe off all residue immediately, wash thoroughly with soapy water and rinse several times.

Warning

1. Do not use for cleaning product's surface abrasive cleaners, water closet cleaners, ceramic tile cleaners or rust cleaners.

2. Do not use cleaning agents that contain the following harsh ingredients: hydrochloric acid, sulfuric acid, hydrofluoric acid, phosphoric acid, or sodium hydroxide.